

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection - Summary Report

Operation: Hosmer Winery WATER (ID: 308846)
Facility Name: hosmer winery inc.
Facility Code: 49-8711
Facility Address: 6999 ROUTE 89 OVID, NY 14521

To the Attention of:

Sanitary Survey

Date: JAN 20, 2015 03:12 PM
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)
Responsible Person: Maren Hosmer (email: tunk41@aol.com)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 3:05pm, from Bathroom CWT; Chlorine residual - 0.00mg/L mg/l, collection time 3:00pm from Bathroom CWT;

Comments

Total Coliform water sample taken bathroom CWT. Nitrate water sample taken bathroom CWT. UV system efficiency level fluctuating from 60% - 70% efficiency level. Will be noted as a violation if observed during next sanitary survey. It is recommended to have UV system fixed immediately.

END of REPORT

[Submit# 127423] Hosmer Winery WATER (ID 308846) Inspection# 1001637600