

Seneca County Department of Health  
Environmental Services  
31 Thurber Drive , Waterloo,, NY 13165  
(315) 539 - 1945  
jbates@co.seneca.ny.us

## Public Water Supply Inspection - Summary Report

Operation: Buttonwood Grove Winery (ID: 498892 )  
Facility Name: buttonwood grove winery  
Facility Code: 4930555  
Facility Address: 5986 State Route Romulus, NY 14541

To the Attention of:

### Sanitary Survey

Date: MAR 25, 2015 03:28 PM  
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)  
Responsible Person: john wenner (email: )

### Summary

Number of public health hazards found: 0  
Number of public health hazards NOT corrected:  
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

### Code Requirements

### Inspector Findings

### Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - Yes; Coliform surveillance sample collected - Yes, collection time 12:29pm, from Tasting room CWT; Chlorine residual - 2.75 mg/l, collection time 2:20pm from Tasting Room CWT;

### Comments

Total Coliform water sample taken Tasting room CWT. Nitrate water sample Tasting room CWT. Well inspected, found to have improper cap. Proper vented cap needs to be installed. Reviewed proper sampling procedures, quarterly requirements, and operation report requirements.

END of REPORT

[Submit# 131418] Buttonwood Grove Winery (ID 498892) Inspection# 1001652471