

Seneca County Department of Health  
Environmental Services  
31 Thurber Drive , Waterloo,, NY 13165  
(315) 539 - 1945  
jbates@co.seneca.ny.us

## Public Water Supply Inspection - Summary Report

Operation: Glenwood Foods (ID: 449861 )  
Facility Name: glenwood foods  
Facility Code: ag-55  
Facility Address: State Route 318

To the Attention of:  
Carl Martin  
2961 Rt. 318  
Seneca Falls , NY 13148-

Sanitary Survey  
Date: APR 07, 2015 12:54 PM  
Inspector: Melissa Brand (mbrand@co.seneca.ny.us)  
Responsible Person: Christalynn Zimmerman (email: )

Summary  
Number of public health hazards found: 0  
Number of public health hazards NOT corrected:  
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

### Code Requirements

### Inspector Findings

### Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 1:00 pm, from Handwashing Sink; Chlorine residual - 0.0 mg/l, collection time from handwash sink;

### Comments

Sample collected for T. Coliform and for Nitrate

END of REPORT

[Submit# 132261] Glenwood Foods (ID 449861) Inspection# 1001653867