

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us
Swimming Pool Inspection - Summary Report

Operation: HAMPTON INN SWIMMING POOL (ID: 803221)
Facility Name: HAMPTON INN
Facility Code: 49-1079
Facility Address: 1950 BALSLEY ROAD SENECA FALLS, NY 13148

To the Attention of:
KELLY WOODWORTH
1950 BALSLEY ROAD
SENECA FALLS , NY 13148-

Inspection

Date: JUN 22, 2015 12:10 PM
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)
Responsible Person: Gino Tranelli (email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected: 0
Number of other violations found: 1

Each item found in violation is reported below along with the code requirement.

FILTER ROOM & EQUIPMENT

ITEM # 47 WAS FOUND IN VIOLATION 1 TIME(S).

Violation Item was not applicable/reviewed/evaluated/observed at the time of inspection.

Code Requirements

Chemical Feed Equipment Operated/Maintained {6-1.11(c)(1), (2), (d), 6-1.10(a), (b)}

Inspector Findings

Acid feed container did not have an overflow container vessel. Advised Hampton to install overflow vessel as soon as possible.

Additional Information Collected During Inspection

Pool/Spa water temperature - 88 degrees Fahrenheit; Flow meter reading (gpm) - 75; Free chlorine/bromine - 3 mg/L; PH - 7.4; Total alkalinity - 100 mg/L; Calcium hardness - 525 mg/L; Temporary Residence/Campground - No; Homeowner exemption - No;

Comments

Acid holding tank needs overflow container located in Pool Equipment room.

END of REPORT

[Submit# 137543] HAMPTON INN SWIMMING POOL (ID 803221) Inspection# 1001670276