

Seneca County Department of Health  
Environmental Services  
31 Thurber Drive , Waterloo,, NY 13165  
(315) 539 - 1945  
jbates@co.seneca.ny.us

## Swimming Pool Inspection - Summary Report

Operation: HILLSIDE SWIMMING POOL (ID: 542380 )  
Facility Name: HILLSIDE CHILDREN'S CENTER  
Facility Code: 49-AD26  
Facility Address: 4887 ROUTE 96A ROMULUS, NY 14541

To the Attention of:  
PATRICIA SCZERBY HILLSIDE CHILDREN'S CENTER  
4887 ROUTE 96A  
ROMULUS , NY 14541-

### Inspection

Date: JUN 24, 2015 10:15 AM  
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)  
Responsible Person: Sarah Spear (email: sspear@Hillside.com )

### Summary

Number of public health hazards found: 0  
Number of public health hazards NOT corrected: 0  
Number of other violations found: 3

Each item found in violation is reported below along with the code requirement.

## FILTER ROOM & EQUIPMENT

ITEM # 46 WAS FOUND IN VIOLATION 2 TIME(S).

Violation Item was not applicable/reviewed/evaluated/observed at the time of inspection.

### Code Requirements

Filters Properly Operated, Maintained; Flow Meter Maintained {6-1.10(a), 6-1.11(b)}

### Inspector Findings

Flow meter was not working. Effluent pressure gage was not working. Advised Hillside to fix as soon as possible.

## POOL OPERATION, MAINTENANCE & SUPERVISION

ITEM # 24 WAS FOUND IN VIOLATION 1 TIME(S).

Violation Item was not applicable/reviewed/evaluated/observed at the time of inspection.

### Code Requirements

Pool Fenced, Self-Closing/Self Latching Gates or Doors {6-1.16}

### Inspector Findings

Main entrance fence to the pool was not self closing. Advised Hillside to install self closing/locking fence as soon as possible.

---

Additional Information Collected During Inspection

Pool/Spa water temperature - 78 degrees Farenheight; Free chlorine/bromine - 2 mg/L; Combined chlorine - 3 mg/L; PH - 7.8; Total alkalinity - 180 mg/L; Calcium hardness - 200 mg/L; Temporary Residence/Campground - No; Homeowner exemption - No;

Comments

---

END of REPORT

[Submit# 137841] HILLSIDE SWIMMING POOL (ID 542380) Inspection# 1001671084