

Seneca County Department of Health  
Environmental Services  
31 Thurber Drive , Waterloo,, NY 13165  
(315) 539 - 1945  
jbates@co.seneca.ny.us  
Campground Inspection - Summary Report

Operation: KENDAIA CAMPGROUND + STORE (ID: 442146 )  
Facility Name: KENDAIA CAMPGROUND + STORE  
Facility Code: NY049-3394  
Facility Address: 5919 96A ROUTE ROMULUS, NY 14541

To the Attention of:  
CYNTHIA & FREDERICK BROWN  
5919 STATE ROUTE 96A  
ROMULUS , NY 14541-

Inspection

Date: MAY 21, 2015 10:21 AM  
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)  
Responsible Person: Madeline Brown (email: )

Summary

Number of public health hazards found: 0  
Number of public health hazards NOT corrected: 0  
Number of other violations found: 2

Each item found in violation is reported below along with the code requirement.

ITEM # 44 WAS FOUND IN VIOLATION 1 TIME(S).

Part or parts of the violation item were observed to be in violation which were corrected at the time of inspection.

Code Requirements

Sewage disposal/treatment facilities adequate, maintained

Inspector Findings

1 sewage line not properly capped. Corrected, capped line.

GENERAL

ITEM # 22 WAS FOUND IN VIOLATION 1 TIME(S).

Part or parts of the violation item were observed to be in violation which were corrected at the time of inspection.

Code Requirements

Electrical service; wiring and fixtures installed, maintained {7-3.17}

Inspector Findings

2 electrical service connections need be maintained and upgraded to be free from the weather.

---

Additional Information Collected During Inspection

Comments

Water system was found to be in compliance. Bathhouse and cabins were found clean. Fire extinguishers and smoke alarms found throughout every cabin.

---

END of REPORT

[Submit# 135862] KENDAIA CAMPGROUND + STORE (ID 442146) Inspection# 1001666062