

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection - Summary Report

Operation: Ginny Lee Cafe (ID: 308171)
Facility Name: ginny lee cafe
Facility Code: 49-AA37
Facility Address: 9322 ROUTE 414

To the Attention of:

Sanitary Survey

Date: JUL 29, 2015 02:30 PM
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)
Responsible Person: Ginny Wagner (email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - Chlorination; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 2:15pm, from kitchen CWT; Chlorine residual - .19 mg/l, collection time 2:12pm from kitchen CWT;

Comments

Total Coliform water sample taken kitchen CWT Nitrate water sample kitchen CWT Well and Chlorination evaluated and found in good condition,

END of REPORT

[Submit# 143512] Ginny Lee Cafe (ID 308171) Inspection# 1001683920