

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection - Summary Report

Operation: O'MALLEY'S CABIN ON THE LAKE WATER (ID: 554370)
Facility Name: o'malley's cabin on the lake
Facility Code: 49-9438
Facility Address: 7938 COUNTY ROAD 153 INTERLAKEN, NY 14847

To the Attention of:

Sanitary Survey

Date: JUL 08, 2015 02:58 PM
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)
Responsible Person: Steven Good (email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

PUBLIC HEALTH HAZARD

VIOLATION OF 5-1.30(a) WAS OBSERVED. (# 7)

Part or parts of the violation item were observed to be in violation which were corrected at the time of inspection.

Code Requirements

5-1.30(a)(b) [ND] Disinfection of a groundwater source. CI and UV equipment is operating as designed. If UV is working, indicator light is On, intensity meter is >70%.

Inspector Findings

Public Health Hazard - UV intensity meter at 46% efficiency. Advised facility to maintain due diligence to maintain efficiency levels above 70% at all times. Corrected, Sleeve cleaned while inspector was present.

VIOLATION OF 5-1.71(b) WAS OBSERVED. (# 14)

Part or parts of the violation item were observed to be in violation which were corrected at the time of inspection.

Code Requirements

5-1.71(b) [SO] Exercise care and due diligence in the operation and maintenance of a public water system

Inspector Findings

Public Health Hazard - Not maintaining proper level of maintenance on Ultra Violet Disinfection system. UV system was in alarm during the last sanitary survey, Sensor was not functioning properly.

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - Yes; Coliform surveillance sample collected - Yes, collection time 3:05pm, from Kitchen CWT; Chlorine residual - 0.27 mg/l, collection time 3:05pm from Kitchen CWT;

Comments

Total Coliform water sample taken Kitchen CWT. Nitrate water sample taken Kitchen CWT. UV system was not maintaining efficiency levels >70%, Corrected while inspector was present. Sleeve cleaned

END of REPORT

[Submit# 139598] O'MALLEY'S CABIN ON THE LAKE WATER (ID 554370) Inspection# 1001675583