

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection - Summary Report

Operation: Zugibe Winery (ID: 796649)
Facility Name: zugibe vineyards
Facility Code: 49-6042
Facility Address:

To the Attention of:

Sanitary Survey

Date: AUG 05, 2015 02:04 PM

Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)

Responsible Person: Brendan Zugibe (email: Brendan@zugibevineyards.com)

Summary

Number of public health hazards found: 0

Number of public health hazards NOT corrected:

Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 2:03pm, from tasting room cwt; Chlorine residual - 0 mg/l, collection time 2:00pm from tasting room cwt;

Comments

Total coliform water sample taken tasting room cwt. Nitrate water sample taken tasting room cwt. UV light was inspected and found in good condition. Extra bulb and sleeve on-site. Evaluated the well and was in compliance with the code. Reviewed operation report and it was noted the 2nd sheet has not been filled out for submission in previous reports. Future operations will have 2nd page filled out per Brendan Zugibe.

END of REPORT

[Submit# 144882] Zugibe Winery (ID 796649) Inspection# 1001686738