

Seneca County Department of Health  
Environmental Services  
31 Thurber Drive , Waterloo,, NY 13165  
(315) 539 - 1945  
jbates@co.seneca.ny.us

## Public Water Supply Inspection -- Summary Report

Operation: Hosmer Winery WATER (ID: 308846 )  
Facility Name: HOSMER WINERY INC.  
Facility Code: 49-8711  
Facility Address: 6999 ROUTE 89 OVID, NY 14521

To the Attention of:

### Sanitary Survey

Date: MAY 18, 2016 10:43 AM  
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)  
Responsible Person: Cameron Hosmer  
(email: cameron@hosmerwinery.com )

### Summary

Number of public health hazards found: 0  
Number of public health hazards NOT corrected:  
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

### Code Requirements

### Inspector Findings

---

### Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 10:49am, from Tasting Room Sink; Chlorine residual - 0 mg/l, collection time 10:30am from tasting room sink;

### Comments

Total Coliform Water sample taken.  
Nitrate water sample taken.  
UV Light was functioning properly.  
Well was inspected and found in good condition

---

END of REPORT