

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection -- Summary Report

Operation: Knapp Winery (ID: 308234)
Facility Name: KNAPP VINEYARDS RESTAURANT
Facility Code: 49-AA48
Facility Address: 2770 COUNTY ROAD 128 ROMULUS, NY 14541

To the Attention of:

Sanitary Survey

Date: AUG 15, 2016 02:02 PM
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)
Responsible Person: Roy cuffe
(email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 2:00pm, from Kitchen CWT; Chlorine residual - 0 mg/l, collection time 1:45pm from Kitchen CWT;

Comments

Total Coliform water sample taken.
Nitrate water sample taken.

END of REPORT

[Submit# 227952] Knapp Winery (ID 308234) Inspection# 1001864854