

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection -- Summary Report

Operation: SUNRISE CAFE WATER (ID: 518172)
Facility Name: SUNRISE CAFE
Facility Code: 49-9101
Facility Address: 9632 ROUTE 96 TRUMANSBURG, NY 14886

To the Attention of:

Sanitary Survey

Date: AUG 16, 2016 01:53 PM
Inspector: Melissa Brown (mbrand@co.seneca.ny.us)
Responsible Person: Randy Smith
(email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - Chlorination; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 1:52, from kitchen cwt; Chlorine residual - 0.56 mg/l, collection time from ;

Comments

RTCR paperwork delivered and signed.

END of REPORT

[Submit# 228951] SUNRISE CAFE WATER (ID 518172) Inspection# 1001865954