

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection - Summary Report

Operation: Montezuma Winery - water (ID: 754827)
Facility Name: montezuma winery
Facility Code: 49-5124
Facility Address: 2981 Auburn Rd. Seneca Falls, NY 13148

To the Attention of:

Sanitary Survey

Date: APR 22, 2015 10:37 AM
Inspector: Melissa Brand (mbrand@co.seneca.ny.us)
Responsible Person: George Martin (email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 10:36 am, from Kitchen CWT; Chlorine residual - 0.0 mg/l, collection time from ;

Comments

T. coliform sample taken at time of sanitary survey

END of REPORT

[Submit# 133053] Montezuma Winery - water (ID 754827) Inspection# 1001654662