

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection - Summary Report

Operation: Poplar Ridge Winery (ID: 308849)
Facility Name: poplar ridge winery
Facility Code: ag-07
Facility Address: Rt. 414

To the Attention of:

David Bagley
9782 Rt. 414
Lodi , ny 14860-

Sanitary Survey

Date: APR 22, 2015 03:23 PM
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)
Responsible Person: Brittany Bagley (email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - No ;Chlorine residual - 0 mg/l, collection time 3:20pm from Utility Room CWT;

Comments

Total Coliform water sample taken Utility Room CWT. Nitrate water sample taken entry point. Well was evaluated- older well, not 18" above the ground. Extra Bulb and Sleeve not on site. Advised to order as soon as possible in case of an emergency. Reviewed operation reports and sampling requirements.

END of REPORT

[Submit# 133095] Poplar Ridge Winery (ID 308849) Inspection# 1001654869