

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection - Summary Report

Operation: Varick Winery (ID: 523413)
Facility Name: varick winery
Facility Code: COBBLE
Facility Address: 5102 89 ROUTE ROMULUS, NY 14541

To the Attention of:
Robert Rozanno

Sanitary Survey

Date: MAY 06, 2015 01:58 PM
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)
Responsible Person: Robert Rozzano (email: rrozzan1@twcny.rr.com)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 2:05pm, from Break Room CWT; Chlorine residual - 0 mg/l, collection time 2:10pm from Break Room CWT;

Comments

Total Coliform water sample taken Break Room CWT. Nitrate water sample taken Break Room Entry point. System is under direct influence from surface water, proper filtration methods were in place to 1 micron Absolute. Extra Bulb and Sleeve on-site.

END of REPORT

[Submit# 133933] Varick Winery (ID 523413) Inspection# 1001659442