

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection - Summary Report

Operation: idol ridge winery water (ID: 887924)
Facility Name: idol ridge winery
Facility Code: 49-69819
Facility Address: 9059 state route 414 Iodi, NY 14860

To the Attention of:
George Martin Montezuma Winery
2981 Auburn Road
Seneca Falls , NY 13148-

Sanitary Survey
Date: JUN 10, 2015 12:41 PM
Inspector: Melissa Brand (mbrand@co.seneca.ny.us)
Responsible Person: Bonnie Forkey (email:)

Summary
Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 12:35 pm, from Tasting room CWT; Chlorine residual - 0.0 mg/l, collection time from ;

Comments

Water sample taken for analysis T.coliform and Nitrate Results to be mailed once we receive them Any questions please call 3155391945

END of REPORT

[Submit# 136424] idol ridge winery water (ID 887924) Inspection# 1001667748