

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection - Summary Report

Operation: KENDAIA CAMPGROUND + STORE WATER (ID: 544968)

Facility Name: kendaia campground + store

Facility Code: NY049-3394

Facility Address: 5919 96A ROUTE ROMULUS, NY 14541

To the Attention of:

Sanitary Survey

Date: MAY 21, 2015 10:11 AM

Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)

Responsible Person: Madeline Brown (email:)

Summary

Number of public health hazards found: 0

Number of public health hazards NOT corrected:

Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - Chlorination; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 10:13am, from Cabin 1 Kitchen CWT; Chlorine residual - 0.56 mg/l, collection time 10:15am from Cabin 1 Kitchen CWT;

Comments

Total Coliform water sample taken Cabin 1 Kitchen CWT. Nitrate water sample taken Cabin 1 Kitchen CWT. Holding tank was evaluated and found in good condition. Water is being supplied by Willy's Water delivery service.

END of REPORT

[Submit# 135861] KENDAIA CAMPGROUND + STORE WATER (ID 544968) Inspection# 1001666050