

Seneca County Department of Health  
Environmental Services  
31 Thurber Drive , Waterloo,, NY 13165  
(315) 539 - 1945  
jbates@co.seneca.ny.us

## Public Water Supply Inspection - Summary Report

Operation: SHADY GLEN BAKERY water (ID: 769642 )  
Facility Name: shady glen bakery  
Facility Code: 49-0285  
Facility Address: 5929 ROUTE 414 ROMULUS, NY 14541

To the Attention of:

### Sanitary Survey

Date: JUN 02, 2015 03:07 PM  
Inspector: Melissa Brand (mbrand@co.seneca.ny.us)  
Responsible Person: Levi Yoder (email: )

### Summary

Number of public health hazards found: 0  
Number of public health hazards NOT corrected:  
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

### Code Requirements

### Inspector Findings

### Additional Information Collected During Inspection

Water System Information: Type of disinfection - Chlorination; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 3:10 pm, from Bakery CWT; Chlorine residual - .49 mg/l, collection time from ;

### Comments

END of REPORT

[Submit# 135781] SHADY GLEN BAKERY water (ID 769642) Inspection# 1001665413