

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection - Summary Report

Operation: SHALESTONE VINEYARDS (ID: 427306)
Facility Name: shalestone vineyards
Facility Code: 49-427306
Facility Address: 9681 Route 414 Lodi, NY 14860

To the Attention of:

Sanitary Survey

Date: JUN 24, 2015 03:05 PM
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)
Responsible Person: Kate Thomas (email: shalestone@empacc.net)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - None; Source Type - Not indicated; 4- Log Treatment installed - Not indicated; Coliform surveillance sample collected - No ;

Comments

Total Coliform water sample taken tasting room CWT. Nitrate water sample taken Entry Point. Extra UV bulb on-site. Shalestone installed a new water softener.

END of REPORT

[Submit# 137913] SHALESTONE VINEYARDS (ID 427306) Inspection# 1001671274