

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection - Summary Report

Operation: Caywood Vineyard (ID: 859196)
Facility Name: caywood vineyard
Facility Code: 49agm
Facility Address: 9666 414 ROUTE Lodi, NY 14860

To the Attention of:

Sanitary Survey

Date: JUL 29, 2015 03:41 PM
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)
Responsible Person: Peggy Bond (email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 3:35pm, from Mens Lav CWT; Chlorine residual - 0 mg/l, collection time 2:40 from Mens LAV CWT;

Comments

Total Coliform water sample taken mens lav CWT. Nitrate water sample taken mens lav CWT. UV system and well evaluated and found to be in good condition

END of REPORT

[Submit# 143511] Caywood Vineyard (ID 859196) Inspection# 1001683922