

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection - Summary Report

Operation: Eremita Winery (ID: 798722)
Facility Name: eremita winery
Facility Code: 49-AD61
Facility Address: Main STREET Lodi, NY 14847

To the Attention of:

Sanitary Survey

Date: OCT 21, 2015 04:04 PM
Inspector: Melissa Brand (mbrand@co.seneca.ny.us)
Responsible Person: Josh Parker
(email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 11:20 am, from Bar CWT;

Comments

Sample collected for compliance Filter changed. Leak in filter casing discovered during inspection. Will repair.

END of REPORT

[Submit# 155509] Eremita Winery (ID 798722) Inspection# 1001757905