

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us
Public Water Supply Inspection - Summary Report

Operation: SUNNY Happy landing convenience (ID: 308842)
Facility Name: sunny happy landing convenienc
Facility Code: 49-225687
Facility Address: 7567 County Road 139 Ovid, NY 14521

To the Attention of:

Sanitary Survey

Date: JAN 27, 2016 01:56 PM
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)
Responsible Person: Satish Patel
(email: happylanding001@gmail.com)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 9:45am, from Utility room CWT; Chlorine residual - 0 mg/l, collection time 9:34am from Utility Room CWT;

Comments

Total Coliform water sample taken Utility CWT. Nitrate water sample taken Entry Point. UV Light inspected and found in good condition.

END of REPORT

[Submit# 172552] SUNNY Happy landing convenience (ID 308842) Inspection# 1001790348