

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection -- Summary Report

Operation: Poplar Ridge Winery (ID: 308849)
Facility Name: Poplar Ridge Winery
Facility Code: ag-07
Facility Address: Rt. 414

To the Attention of:
David Bagley
9782 Rt. 414
Lodi , ny 14860-

Sanitary Survey
Date: APR 28, 2016 11:49 AM
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)
Responsible Person: Alicia Kelley
(email:)

Summary
Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 2:51pm, from Break Room CWT; Chlorine residual - 0 mg/l, collection time 2:47pm from Break Room CWT;

Comments

Well and UV light inspected and found in good condition.
Total Coliform water sample taken Break Room CWT.
Nitrate water sample taken CWT.

END of REPORT