

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection -- Summary Report

Operation: Boundry Breaks Winery (ID: 923881)
Facility Name: Boundry Breaks Winery
Facility Code: 49-AD76
Facility Address: 1428 Porter-Covert ROAD Lodi, NY 14860

To the Attention of:

Sanitary Survey

Date: JUN 01, 2016 08:40 AM
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)
Responsible Person: Russ Denmark
(email: rkginc@verizon.net)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - Chlorination; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 9:37am, from Tasting Room CWT; Chlorine residual - 2.20 mg/l, collection time 9:30am from tasting room CWT;

Comments

Total Coliform water sample taken tasting room CWT.
Nitrate - Nitrite water sample taken Entry Point.
Well was inspected and GPS position taken.
Completed works inspection completed for the chlorination system.

END of REPORT