

Seneca County Department of Health  
Environmental Services  
31 Thurber Drive , Waterloo,, NY 13165  
(315) 539 - 1945  
jbates@co.seneca.ny.us

## Public Water Supply Inspection -- Summary Report

Operation: Buttonwood Grove Winery WATER (ID: 498892 )  
Facility Name: BUTTONWOOD GROVE WINERY  
Facility Code: 4930555  
Facility Address: 5986 STATE ROUTE 89 ROMULUS, NY 14541

To the Attention of:

### Sanitary Survey

Date: JUN 01, 2016 02:39 PM

Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)

Responsible Person: Dave Pittard

(email: )

### Summary

Number of public health hazards found: 0

Number of public health hazards NOT corrected:

Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

### Code Requirements

### Inspector Findings

### Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 2:40pm, from Tasting Room CWT; Chlorine residual - 0.71 mg/l, collection time 2:45pm from Tasting Room CWT;

### Comments

Total Coliform Tasting Room CWT.

Nitrate water sample Entry Point.

Well and UV system inspected and found in good condition.

END of REPORT