

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us
Campground Inspection -- Summary Report

Operation: JUNIUS PONDS CABINS/CAMPGROUND (ID: 308152)
Facility Name: JUNIUS PONDS CABINS/CAMPGROUND LLC
Facility Code: 49-AJ82
Facility Address: 1475 WEST TOWNLINE ROAD PHELPS, NY 14532

To the Attention of:
ERIC DADSON
1475 WEST TOWNLINE ROAD
PHELPS , NY 14532-

Inspection

Date: JUN 01, 2016 02:02 PM
Inspector: Melissa Brand (mbrand@co.seneca.ny.us)
Responsible Person: WILL BE MAILED
(email:)

Summary

Number of public health hazards found: 4
Number of public health hazards NOT corrected: 0
Number of other violations found: 7
Reinspection is required.

Each item found in violation is reported below along with the code requirement.

PUBLIC HEALTH HAZARDS

A public health hazard is any condition that poses an imminent threat to the health or safety of the public. An owner/operator of a regulated facility must immediately correct all public health hazards or take actions to prevent exposure to the hazard.

ITEM # 7 WAS FOUND IN VIOLATION 4 TIME(S). PUBLIC HEALTH HAZARD

All or parts of the violation item are IN violation.

Code Requirements

Absence of cross connections - potable water supply {7-3.5(b)(1)(vii)}

Inspector Findings

Hydroflush units installed on campers at 209,211,228,229. These devices are not permitted to be used at regulated facilities. Hydroflush devices create a DIRECT connection between the potable water supply and the RV waste holding tank. In addition, the anti-siphon valve available for use with these devices does not adequately protect the water supply from such a high degree of hazard. Pictures of this device have been enclosed with the inspection report.

NON-PUBLIC WATER SYSTEM (INDIVIDUAL ON-SITE)

ITEM # 31 WAS FOUND IN VIOLATION 4 TIME(S).

All or parts of the violation item are IN violation.

Code Requirements

Free of cross-connections

Inspector Findings

Hydroflush units installed on campers at 209,211,228,229. These devices are not permitted to be used at regulated facilities. Hydroflush devices create a DIRECT connection between the potable water supply and the RV waste holding tank. In addition, the anti-siphon valve available for use with these devices does not adequately protect the water supply from such a high degree of hazard. Pictures of this device have been enclosed with the inspection report.

OTHER

ITEM # 50 WAS FOUND IN VIOLATION 2 TIME(S).

All or parts of the violation item are IN violation.

Code Requirements

Handwash facilities - adequate number, location, maintained

Inspector Findings

Men's and ladies room by cabins did not have soap for hand washing.

WATER SUPPLY - GENERAL

ITEM # 38 WAS FOUND IN VIOLATION 1 TIME(S).

All or parts of the violation item are IN violation.

Code Requirements

Interruptions, changes in source/treatments, notification within 24 hrs.

Inspector Findings

Transformer blown on Memorial Day weekend. Water services were interrupted during this time. power restored by Wednesday June 1. Restoration of services should be followed up by water samples to ensure water quality and safety.

Additional Information Collected During Inspection

Comments

END of REPORT

[Submit# 201000] JUNIUS PONDS CABINS/CAMPGROUND (ID 308152) Inspection# 1001828944