

Seneca County Department of Health  
Environmental Services  
31 Thurber Drive , Waterloo,, NY 13165  
(315) 539 - 1945  
jbates@co.seneca.ny.us

## Public Water Supply Inspection -- Summary Report

Operation: KENDAIA CAMPGROUND + STORE WATER (ID: 544968 )

Facility Name: KENDAIA CAMPGROUND + STORE

Facility Code: NY049-3394

Facility Address: 5919 96A ROUTE ROMULUS, NY 14541

To the Attention of:

### Sanitary Survey

Date: JUN 08, 2016 03:56 PM

Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)

Responsible Person: Madeline Brown

(email: )

### Summary

Number of public health hazards found: 0

Number of public health hazards NOT corrected:

Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

### Code Requirements

### Inspector Findings

### Additional Information Collected During Inspection

Water System Information: Type of disinfection - Chlorination; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 4:00pm, from Cabin 2 CWT; Chlorine residual - .71 mg/l, collection time 4:05pm from Cabin 2 CWT;

### Comments

Holding tank inspected and found in good condition

Total Coliform water sample taken.

Nitrate water sample taken.

END of REPORT

[Submit# 202782] KENDAIA CAMPGROUND + STORE WATER (ID 544968) Inspection# 1001831021