

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection -- Summary Report

Operation: King's Garden Vineyard (ID: 663508)
Facility Name: King's Garden Vineyard
Facility Code: 49-7444
Facility Address: 9085 NYS 414 ROUTE Lodi, NY 14860

To the Attention of:

Sanitary Survey

Date: JUN 13, 2016 02:27 PM
Inspector: Arthur Sinicropi (asinicropi@co.seneca.ny.us)
Responsible Person: Wendy Wade
(email: oleksyn.cor@gmail.com)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Not indicated; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 2:28pm, from men's lave CWT; Chlorine residual - 0 mg/l, collection time 2:30pm from Men's Lave CWT;

Comments

Total Coliform water sample taken.
Nitrate water sample taken.
Well and UV system was found in good condition

END of REPORT

[Submit# 203787] King's Garden Vineyard (ID 663508) Inspection# 1001832274