

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us
Swimming Pool Inspection -- Summary Report

Operation: HAMPTON INN SWIMMING POOL (ID: 803221)
Facility Name: HAMPTON INN
Facility Code: 49-1079
Facility Address: 1950 BALSLEY ROAD SENECA FALLS, NY 13148

To the Attention of:
KELLY WOODWORTH
1950 BALSLEY ROAD
SENECA FALLS , NY 13148-

Inspection

Date: AUG 11, 2016 12:21 PM
Inspector: Melissa Brown (mbrand@co.seneca.ny.us)
Responsible Person: Gino Tranelli
(email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected: 0
Number of other violations found: 4

Each item found in violation is reported below along with the code requirement.

FILTER ROOM & EQUIPMENT

ITEM # 49 WAS FOUND IN VIOLATION 1 TIME(S).

All or parts of the violation item are IN violation.

Code Requirements

Chemicals Approved, Proper Storage/Handling/Labeling {6-1.11(c)(1)-(4), (d)}

Inspector Findings

catch basin needed for acid mix. In the event of a puncture the catch basin would prevent acid from spilling onto floor.

POOL OPERATION, MAINTENANCE & SUPERVISION

ITEM # 31 WAS FOUND IN VIOLATION 1 TIME(S).

All or parts of the violation item are IN violation.

Code Requirements

Adequate Lighting Surface Glare & Reflection Prevented {6-1.17(d), (e), (f), (h)}

Inspector Findings

Windows in pool area create glare on pool surface. Discussed options for reducing glare. No definite solution was given at this time.

Additional Information Collected During Inspection

Pool/Spa water temperature - 86 degrees Fahrenheit; Flow meter reading (gpm) - 80; Free chlorine/bromine - 10 mg/L; PH - 7.7; Total alkalinity - 110 mg/L; Calcium hardness - 420 mg/L; Temporary Residence/Campground - No; Homeowner exemption - No;

Comments

END of REPORT

[Submit# 225217] HAMPTON INN SWIMMING POOL (ID 803221) Inspection# 2003721380