

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Swimming Pool Inspection -- Summary Report

Operation: HILLSIDE SWIMMING POOL (ID: 542380)
Facility Name: HILLSIDE CHILDREN'S CENTER
Facility Code: 49-AD26
Facility Address: 4887 ROUTE 96A ROMULUS, NY 14541

To the Attention of:
SARAH SPEAR
HILLSIDE CHILDREN'S CENTER 4887 ROUTE 96A
ROMULUS , NY 14541-

Inspection

Date: AUG 30, 2016 11:43 AM
Inspector: Julie Hoster (jhoster@co.seneca.ny.us)
Responsible Person: Sarah Spear
(email:)

Summary

Number of public health hazards found: 1
Number of public health hazards NOT corrected: 0
Number of other violations found: 2

Each item found in violation is reported below along with the code requirement.

PUBLIC HEALTH HAZARDS

A public health hazard is any condition that poses an imminent threat to the health or safety of the public. An owner/operator of a regulated facility must immediately correct all public health hazards or take actions to prevent exposure to the hazard.

ITEM # 2 WAS FOUND IN VIOLATION 1 TIME(s). PUBLIC HEALTH HAZARD

Part or parts of the violation item were observed to be in violation which were corrected at the time of inspection.

Code Requirements

Minimum Disinfectant Residual Provided {6-1.4(b)(2)}

Inspector Findings

chlorine level at <.5 ppm CORRECTED: brought CI level to >.6

POOL OPERATION, MAINTENANCE & SUPERVISION

ITEM # 24 WAS FOUND IN VIOLATION 1 TIME(s).

Part or parts of the violation item were observed to be in violation which were corrected at the time of inspection.

Code Requirements

Pool Fenced, Self-Closing/Self Latching Gates or Doors {6-1.16}

Inspector Findings

gate does not self latch; a work order is currently in for it's repair

ITEM # 39 WAS FOUND IN VIOLATION 1 TIME(S).

Part or parts of the violation item were observed to be in violation which were corrected at the time of inspection.

Code Requirements

Test Kits/Testing - Adequate {6-1.11(c)(5)}

Inspector Findings

testing tube of test kit dis colored does not allow for proper observation of Cl level

Additional Information Collected During Inspection

Free chlorine/bromine - 1.0 mg/L; PH - 7.6; Total alkalinity - 80 mg/L; Calcium hardness - 130 mg/L; Supervision level - IIb; Temporary Residence/Campground - No; Homeowner exemption - No;

Comments

discussed lifeguard scanning techniques and potential blind spots while guarding; discussed swimmers posing a distraction to lifeguards and the potential for underwater blackout with breath holding

END of REPORT

[Submit# 231516] HILLSIDE SWIMMING POOL (ID 542380) Inspection# 1001869154