

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Public Water Supply Inspection -- Summary Report

Operation: Varick Winery (ID: 523413)
Facility Name: VARICK WINERY
Facility Code: COBBLE
Facility Address: 5102 89 ROUTE ROMULUS, NY 14541

To the Attention of:

Sanitary Survey

Date: AUG 30, 2016 02:05 PM
Inspector: Thomas Scoles (tscoles@co.seneca.ny.us)
Responsible Person: Lori Horton
(email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected:
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - UV; Source Type - Ground water under the direct influence of surface water; 4- Log Treatment installed - No; Coliform surveillance sample collected - Yes, collection time 14:15, from tasting room bar;

Comments

Total Coliform surv. sample collected. Nitrate sample collected. Total Coliform sample plan past due.

END of REPORT

[Submit# 231536] Varick Winery (ID 523413) Inspection# 1001869175