

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us
Public Water Supply Inspection -- Summary Report

Operation: idol ridge winery water (ID: 887924)
Facility Name: idol ridge winery
Facility Code: 49-69819 Facility Email: None
Facility Address: 9059 state route 414 Iodi, NY 14860

To the Attention of:
George Martin Montezuma Winery
2981 Auburn Road
Seneca Falls , NY 13148- Owner/Operator Email: None

Sanitary Survey
Date: DEC 19, 2016 03:00 AM
Inspector: Melissa Brown (mbrown@co.seneca.ny.us)
Responsible Person: to be mailed
(email:)

Summary
Number of public health hazards found: 0
Number of public health hazards NOT corrected: 0
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Water System Information: Type of disinfection - None; Source Type - Not indicated; 4- Log Treatment installed - Not indicated; Coliform surveillance sample collected - No ;

Comments

END of REPORT

[Submit# 258870] idol ridge winery water (ID 887924) Inspection# 1001928424